



Istog Earthquake of March 10, 2010

Shemsi Mustafa^{1,*}, Zenun Elezaj²

¹*Ministry of Economic Development, Seismological Institute of Kosovo;* ²*Faculty of Mining and Metallurgy-Mitrovicë, Kosovo*

Received September 07, 2011; Accepted December 12, 2011

Abstract: Essential seismological and seismotectonic features of Istog earthquake of March 10, 2010, are presented in this paper. Some characteristics of structural damages and related engineering aspects are dealt with, as well.

Keywords: *Istog earthquake, Geologic condition, Seismotectonics, Structural damages.*

* Corresponding: E-Mail: shemsi_mustafa@hotmail.com;